



Referencia de Obra

Job Reference

Ref. Nº 520.00

CONCRETE REPAIR WITH MAXGROUT FOOTBALL STADIUM “EL MOLINÓN”



Place: “El Molinón”, Gijón (SPAIN)

2010

Description: Concrete repair by fluid structural repair mortar

System: **MAXGROUT®**



Referencia de Obra

Job Reference

Ref. Nº 520.00





Referencia de Obra

Job Reference

Ref. Nº 520.00

